



VEHICLE INSPECTION REPORT

AF56URM

Volvo XC90 2.4 D5 SE 5dr Geartronic [185]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2006	Colour	BLUE	Service history	None
Year	2006	VIN	YV1CZ714671333693	MOT Due	11/11/2026
Mileage	172,020 Miles Warranted	Body Style	Estate	Gearbox	AUTOMATIC
Fuel Type	Diesel	Keys	1	Gears	6

No Service History Radio faulty
 Engine system service required message displayed on dash
 Bonnet catch broken
 Parking sensors faulty
 Smoking

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Leather seat trim
- Heated front seat
- Service indicator
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Fascia Trim
Damaged
Replace



2: Seat Base Cover osf
Scuffed
Over 25mm



3: Seat Back Cover osr
Holed
Over 3mm



4: Seat Base Cover osr
Holed
Over 3mm



5: Seat Base Cover nsf
Scuffed
Over 25mm



6: Fascia Trim
Damaged
Replace



7: Bonnet
Scratched
Over 25mm Thru Paint



8: Bumper Front
Scratched
Over 100mm Thru Paint



9: Wing nsf
Scratched
Over 25mm Thru Paint



10: Wheel nsf
Scratched
Over 50mm



11: Door Mirror Assy nsf
Broken
Replace



12: Door nsf
Dented
With Paint Damage



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Wheel nsr
Corroded
Light



15: Qtr Panel nsr
Dented
Between 10mm + 30mm



16: Bumper Rear
Dented
With Paint Damage



17: Bumper Rear Moulding
Broken
Replace



18: Tailgate
Dented
With Paint Damage



19: Qtr Panel osr
Dented
Between 10mm + 30mm



20: Wheel osr
Scratched
Over 50mm



21: Door osr
Scratched
Over 25mm Thru Paint



22: Door osf
Dented
With Paint Damage



23: Wing osf
Scratched
Over 25mm Thru Paint



24: Wheel osf
Scratched
Up To 50mm



25: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	Fault
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	Fault
		Steering	OK