



# VEHICLE INSPECTION REPORT

**GY71HUV**

## Volvo V60 2.0 T6 Recharge PHEV R DESIGN 5dr AWD Auto

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	25/11/2021	Body Style	Estate	Last service miles	81,327
Year	2021	Keys	2	MOT Due	09/02/2027
Mileage	93,138 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	8
Colour	WHITE	Number of stamps	5		
VIN	YV1ZWBFDVN1482107	Last service date	12/06/2025		

### £90 ADDITIONAL FEE

Last service 12/06/2025 at 81,327 miles- 5 main dealer services. Book Type 3 charging cable only  
 Charging port cover will not close properly

### Tyres



NSF	YOKOHAMA	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	YOKOHAMA	5.0mm
OSR	YOKOHAMA	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: A Post ns  
Chipped  
1 To 5



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Up To 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Bumper Rear  
Cracked  
UpTo 25mm



10: Wheel osr  
Scratched  
Over 50mm



11: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



12: Door osf  
Dented  
Over 30mm



13: Wheel osf  
Scratched  
Over 50mm



14: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK