



# VEHICLE INSPECTION REPORT

**GN67ZPX**

## Lexus CT 200h 1.8 Advance 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	05/09/2017	Body Style	Hatchback	Last service miles	23,384
Year	2017	Keys	2	MOT Due	04/09/2026
Mileage	23,623 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	8	Doors	5
VIN	JTHKD5BH102307919	Last service date	24/09/2025		

£100 ADDITIONAL FEE

Last service 24/09/2025 at 23,384 miles- 8 main dealer services. Book

### Tyres

NSF	APOLLO	6.0mm
NSR	YOKOHAMA	Damaged
OSF	APOLLO	6.0mm
OSR	YOKOHAMA	Damaged
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wing nsf  
Poor Previous Repair  
Poor Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Poor Previous Repair  
Rippled UpTo 30%



6: Tyre osr  
Damaged  
Replace



7: Tyre nsr  
Damaged  
Replace



8: A Post ns  
Scratched  
UpTo 25mm Thru Paint



9: Door nsr  
Poor Previous Repair  
Rippled UpTo 30%



10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Poor Previous Repair  
Rippled UpTo 30%



12: Bumper Rear  
Scratched  
Over 100mm Thru Paint



13: Tailgate  
Scratched  
Over 25mm Thru Paint



14: Qtr Panel osr  
Chipped  
1 To 5



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Door osf  
Scratched  
Over 25mm Thru Paint



18: Wing osf  
Scratched  
Over 25mm Thru Paint



19: Wheel osf  
Scratched  
Over 50mm



20: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



21: Screen Front  
Chipped  
UpTo 10mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK