



# VEHICLE INSPECTION REPORT

**LM57JZT**

## Volkswagen Golf 1.6 Match FSI 5dr

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	22/01/2008	Body Style	Hatchback	Last service miles	43,305
Year	2008	Keys	1	MOT Due	10/08/2026
Mileage	111,212 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	8	Doors	5
VIN	WVWZZZ1KZ8P048651	Last service date	05/08/2016		

### £90 ADDITIONAL FEE

Last service 05/08/2016 at 43,305 miles- 8 main dealer services. Print Driver side window faulty  
 High clutch

### Tyres

NSF	BUDGET	6.0mm
NSR	FALKEN	4.0mm
OSF	MAXXIS	5.0mm
OSR	MAXXIS	5.0mm
Spare		

## Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Seat Back Cover osf  
Scuffed  
Over 25mm



3: Bonnet  
Chipped  
Multiple Chips



4: Bumper Front  
Poor Previous Repair  
Paint Flake



5: Wing nsf  
Rusted  
Over 5mm



6: Wheel nsf  
Scratched  
Over 50mm



7: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



8: Sill ns  
Rusted  
Over 5mm



9: Door nsf  
Dented  
Over 30mm



10: A Post ns  
Chipped  
1 To 5



11: Door nsr  
Dented  
Over 30mm



12: Wheel nsr  
Scratched  
Up To 50mm



13: Qtr Panel osr  
Scratched  
Up To 25mm Thru Paint



14: Bumper Rear  
Dented  
With Paint Damage



15: Qtr Panel osr  
Dented  
With Paint Damage



16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Scratched  
Over 25mm Thru Paint



18: Door osf  
Dented  
Between 10mm + 30mm



19: Door osf  
Scratched  
Up To 25mm Thru Paint



20: Roof  
Chipped  
Multiple Chips



21: A Post os  
Chipped  
1 To 5



22: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



23: Wheel osf  
Scratched  
Over 50mm



24: Sill os  
Rusted  
Over 5mm



25: Wing osf  
Rusted  
Over 5mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK