



VEHICLE INSPECTION REPORT

BG19SOA

Ford Galaxy 2.0 EcoBlue 150 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/07/2019	Body Style	MPV	Last service miles	75,783
Year	2019	Keys	1	MOT Due	03/10/2026
Mileage	78,691 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	4		
VIN	WF0KXXWPCKKY73352	Last service date	25/09/2025		

£100 ADDITIONAL FEE.

Last service 25/09/2025 at 75,783 miles- 4 services (3 main dealer) Book and print handbrake fault
Intake pipe disconnected

Tyres

NSF	BUDGET	Worn
NSR	MICHELIN	3.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Wing nsf
Scratched
Up To 25mm Thru Paint

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
1 To 5

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint




10: Wheel nsr
Scratched
Up To 50mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm




14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Dented
Between 10mm + 30mm



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm



22: Lamp nsr
Broken
Replace



23: Lamp osr
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK