



VEHICLE INSPECTION REPORT

DS69HCL

Mercedes-Benz A Class A180d AMG Line Executive 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/12/2019	Body Style	Saloon	Last service miles	53,188
Year	2019	Keys	2	MOT Due	09/10/2025
Mileage	61,120 Miles Warranted	Service history	Yes	CAP Clean	£13,100.00
Fuel Type	Diesel	Service documents	Printout	CAP Average	£12,000.00
Colour	BLACK	Number of stamps	5	CAP Below	£10,850.00
VIN	W1K1771032J177472	Last service date	22/04/2024	Doors	4

Last Service - 22.04.2024 at 53188 miles (5 main dealer services) Engine tapping and Eml on

Tyres

NSF	BUDGET	4.0mm
NSR	DAVANTI	4.0mm
OSF	BUDGET	3.0mm
OSR	DAVANTI	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Front parking sensor
- PAS
- Telephone
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Central locking
- Heated front seat
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Wheel nsr
Scratched
Over 50mm

No Image

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Chipped
Multiple Chips



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Dented
With Paint Damage



13: Door osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm



15: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK