

VEHICLE INSPECTION REPORT

DY16ZFC

Vauxhall Astra 1.4T 16V 150 Tech Line 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	24/06/2016	Keys	2	CAP Clean	£5,925.00
Year	2016	Service history	Yes	CAP Average	£5,100.00
Mileage	36,370 Miles Warranted	Service documents	Service Book	CAP Below	£4,300.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	AUTOMATIC
Colour	SILVER	Last service date	29/08/2024	Gears	6
VIN	W0LBD6EC3G8078379	Last service miles	33,988	Doors	5
Body Style	Hatchback	MOT Due	04/09/2025		

£100 ADDITIONAL FEE. Last Service: 29/08/2024 at 33988 miles. (7 services (4 main)). Book & print. Eml on and traction control light on Heavy vibration at idle

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

- Cruise control
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

- · Front parking sensor
- Air conditioning
- · Front head restraints
- Solid Paint
- · Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos























Condition Check



Damage Photos



1: Bumper Rear Scratched 25 to 100mm Thru Paint No Image

2: Qtr Panel osr Scratched Over 25mm Not Thru Paint




3: Wheel osr Scratched Over 50mm

No Image

4: Door osr Scratched Over 25mm Not Thru Paint

No Image





7: Bumper Front Chipped Multiple Chips



6: Bonnet Chipped 1 To 5



8: Wheel nsf Scratched Over 50mm



9: Wheel osf Scratched Up To 50mm



10: Door nsfChipped1 To 5

No Image

11: Door nsrScratchedOver 25mm Not Thru Paint

No Image

12: Qtr Panel nsrScratchedOver 25mm Not Thru Paint



13: Wheel nsr Scratched Up To 50mm

Interior

Carpet Condition Seat Condition

Average Average **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK