



VEHICLE INSPECTION REPORT

LT16AMK

Kia Sorento 2.2 CRDi KX-4 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/03/2016	Body Style	Estate	Last service miles	69,521
Year	2016	Keys	2	MOT Due	16/12/2026
Mileage	69,566 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	5		
VIN	KNAPH81BSG5180585	Last service date	22/09/2025		

Last service 22/09/2025 at 69521 miles (5 services (3 main dealer). Book & print.

Tyres

NSF	GOODYEAR	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	GOODYEAR	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Other
N/A
N/A



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



12: Qtr Panel Trim ns
Scuffed
Over 25mm



13: Tailgate
Scratched
UpTo 25mm Thru Paint



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Chipped
Multiple Chips



19: Wheel osf
Scratched
Up To 50mm



20: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		