

# VEHICLE INSPECTION REPORT

**RK62OFX**

## Mercedes-Benz Vito 116CDI Van

nama  
 GRADE  
**5**

| Inspection      |    | Vehicle |          |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT     | Plus VAT |
|                 |    | V5      | Present  |

### Details

|           |                            |                  |                   |                    |            |
|-----------|----------------------------|------------------|-------------------|--------------------|------------|
| Reg. date | 21/09/2012                 | VIN              | WDF63960323703389 | Last service date  | 20/05/2014 |
| Year      | 2012                       | Body Style       | Panel Van         | Last service miles | 37,083     |
| Mileage   | 206,099 Miles<br>Warranted | Keys             | 2                 | MOT Due            | 15/09/2026 |
| Fuel Type | Diesel                     | Service history  | Yes               | Gearbox            | MANUAL     |
| Colour    | WHITE                      | Number of stamps | 2                 | Gears              | 6          |

Last service 20/05/2014 at 37,083 miles- 2 services confirmed by Rossetts Commercials Mercedes-Benz, Eastbourne

### Tyres

|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 5.0mm |
| NSR   | BUDGET | 5.0mm |
| OSF   | RAPID  | 3.0mm |
| OSR   | BUDGET | 4.0mm |
| Spare |        |       |

### Features


- Cruise control
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Paint Flake



2: Bumper Front  
Cracked  
Over 25mm



3: Wing nsf  
Rusted  
Over 5mm



4: Door nsf  
Rusted  
Over 5mm




5: Sill ns  
Rusted  
Over 5mm



6: Door nsr  
Chipped  
Multiple Chips



7: Qtr Panel nsr  
Rusted  
Over 5mm



8: Bumper Rear  
Poor Previous Repair  
Poor Paint



9: Boot Lid  
Dented  
With Paint Damage



10: Qtr Panel osr  
Chipped  
Multiple Chips



11: Lamp osr  
Broken  
Replace



12: Lamp nsr  
Broken  
Replace



13: Qtr Panel Moulding os  
Missing  
Replace



14: Door osr  
Dented  
With Paint Damage



15: Door osf  
Chipped  
Multiple Chips



16: Sill os  
Rusted  
Over 5mm



17: Wing osf  
Poor Previous Repair  
Poor Paint



18: A Post os  
Rusted  
UpTo 5mm



19: Roof  
Rusted  
UpTo 5mm



20: Screen Front  
Chipped  
UpTo 10mm



21: Other  
N/A  
N/A

### Interior

|                         |         |                             |         |
|-------------------------|---------|-----------------------------|---------|
| <b>Carpet Condition</b> | Average | <b>Upholstery Condition</b> | Average |
| <b>Seat Condition</b>   | Average | <b>Odour</b>                | No      |

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |  |    |
|--------------------------|----|--|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio  | OK |
|                          |    | Steering                                       | OK |