



VEHICLE INSPECTION REPORT

AO19ZGA

Nissan Navara Double Cab Pick Up N-Guard 2.3dCi 190 4WD Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present



Details

Reg. date	30/04/2019	Body Style	Pick-up	Last service miles	75,837
Year	2019	Keys	2	MOT Due	08/05/2026
Mileage	90,201 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	5		
VIN	VSKCTND23U0124929	Last service date	20/04/2023		

Last service 20/04/2023 at 75,837 miles- 5 main dealer services. Print As blue message displayed

Tyres

NSF	BFGOODRICH	7.0mm
NSR	BFGOODRICH	Damaged
OSF	BFGOODRICH	7.0mm
OSR	BFGOODRICH	7.0mm
Spare		


Features

- Bluetooth connection
- Park assist camera
- Towbar
- Metallic Paint
- Leather seat trim
- Cruise control
- Rear parking sensor
- Air conditioning
- Drivers airbag
- Heated front seat
- Digital radio
- Front electric windows
- Passenger airbag
- Navigation system
- Electric sunroof
- Rear electric windows
- Central locking

Photos



Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Other
N/A
N/A



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Screen Front
Cracked
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Tailgate
Dented
With Paint Damage



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osf
Scratched
Over 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wing osf
Scratched
Rusted



18: Wheel osf
Scratched
Over 50mm



19: Fogdriving Lamp osf
Broken
Replace



20: Roof
Dented
With Paint Damage



21: Tyre nsr
 Damaged
 Replace

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		