



VEHICLE INSPECTION REPORT

GF65CKN

Peugeot 5008 1.6 BlueHDi 120 Allure 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	28/09/2015	Body Style	MPV	Last service miles	53,313
Year	2015	Keys	1	MOT Due	02/12/2026
Mileage	118,219 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	3		
VIN	VF30EBHZMFS226134	Last service date	17/06/2019		

Last service 17/06/2019 at 53,313 miles- 3 services. Book Fly wheel noisy
 Aftermarket gear stick fitted

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Telephone
- Towbar
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing ofsf
Scratched
Over 25mm Not Thru Paint



2: Wheel ofsf
Scratched
Over 50mm



3: Sill os
Rusted
Over 5mm



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Door osf
Chipped
Edge Chip



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Rusted
Over 5mm



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Tailgate
Dented
Over 30mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door nsf
Scratched
Over 25mm Thru Paint



15: Wing nsf
Scratched
Over 25mm Thru Paint



16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Poor Previous Repair
Paint Flake



18: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		