



VEHICLE INSPECTION REPORT

WO64OTV

Toyota Yaris 1.33 VVT-i Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	10/02/2015	Body Style	Hatchback	Last service miles	41,519
Year	2015	Keys	2	MOT Due	09/02/2027
Mileage	51,754 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	VNKKJ3D370A275829	Last service date	03/01/2024		

£90 ADDITIONAL FEE

Last service 03/01/2024 at 41,519 miles- 5 services (4 main dealer) Book Driver side window faulty
 Traction Control light is on
 Blurry reverse camera

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Central locking
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Up To 25mm Thru Paint




9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door nsr
Dented
Over 30mm



16: Door osf
Dented
Between 10mm + 30mm



17: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK