



# VEHICLE INSPECTION REPORT

**LP72KCC**

## MG Mg 4 SE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	23/12/2022	Body Style	Hatchback	Last service miles	15,591
Year	2022	Keys	2	MOT Due	28/09/2026
Mileage	33,213 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	RED	Number of stamps	1	Doors	5
VIN	LSJWH409XNN218920	Last service date	29/11/2023		

### £90 ADDITIONAL FEE

Last service 29/11/2023 at 15,591 miles- 1 main dealer service. Print Type 2 charging cable

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bumper Front  
Chipped  
Multiple Chips



3: Wheel nsf  
Scratched  
Over 50mm




4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Scratched  
UpTo 25mm Thru Paint



6: Screen Front  
Chipped  
UpTo 10mm



7: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



8: Door nsr  
Scratched  
UpTo 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm




10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Wheel osr  
Scratched  
Over 50mm



12: Door osr  
Poor Previous Repair  
Rippled Up To 30%



13: Door osf  
Poor Previous Repair  
Rippled Up To 30%



14: Wing osf  
Scratched  
Over 25mm Thru Paint



15: Wheel of  
Scratched  
Over 50mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK