



VEHICLE INSPECTION REPORT

BC18ASO

Skoda Octavia 1.5 TSI SE L 5dr

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/06/2018	Body Style	Hatchback	Last service miles	47,282
Year	2018	Keys	3	MOT Due	19/02/2027
Mileage	91,278 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	TMBBR7NE8J0276858	Last service date	09/02/2024		

£90 ADDITIONAL FEE

Last service 09/02/2024 at 47,282 miles- 4 main dealer services. Print Noisy front suspension
 Stop start system faulty message displayed
 Driver side window switch broken

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Full size spare wheel
- Front electric windows
- Steering wheel rake adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Broken
Replace



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
Over 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Dented
UpTo 30mm (Alloy)




10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Boot Lid
Scratched
Over 25mm Thru Paint



13: Door osr
Dented
Over 30mm



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing osf
 Scratched
 UpTo 25mm Thru Paint



16: Screen Front
 Chipped
 UpTo 10mm



17: Switches And Controls
 Broken
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK