



# VEHICLE INSPECTION REPORT

**KY11KDN**

## Mazda 6 2.0 Takuya 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	21/03/2011	Body Style	Hatchback	Last service miles	104,595
Year	2011	Keys	2	MOT Due	13/08/2026
Mileage	134,070 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	8	Doors	5
VIN	JMZGHA4E601452717	Last service date	26/07/2018		

Last service 26/07/2018 at 104,595 miles- 8 main dealer services. Print Steering heavy  
 Boot opening button broken

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Dented  
Over 30mm



3: Door osr  
Scratched  
Over 25mm Thru Paint



4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



7: Tailgate  
Dented  
Over 30mm



8: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsr  
Scratched  
Over 25mm Not Thru Paint



12: Door nsf  
Dented  
Between 10mm + 30mm



13: Door nsf  
Scratched  
Over 25mm Not Thru Paint



14: Wing nsf  
Dented  
With Paint Damage



15: Wheel nsf  
Scratched  
Over 50mm



16: Bumper Front  
Poor Previous Repair  
Poor Paint



17: Bonnet  
Chipped  
Multiple Chips



18: Screen Front  
Chipped  
UpTo 10mm



19: Roof  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	Fault