



VEHICLE INSPECTION REPORT

CK63YNL

Peugeot 2008 1.6 e-HDi Allure 5dr EGC

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/01/2014	Body Style	Hatchback	Last service miles	83,237
Year	2014	Keys	2	MOT Due	19/12/2026
Mileage	110,578 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	VF3CU9HP8DY088421	Last service date	14/12/2022		

Last Service - 14.12.2022 at 83237 miles (4 services) Engine fault - repair needed on dash
Gearbox fault
Service light on

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- PAS
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Dented
Over 2 UpTo 10mm




4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 2 UpTo 10mm




7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Bumper Rear
Chipped
Multiple Chips



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

15: Boot Lid
Scratched
Over 25mm Not Thru Paint



16: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Over 2 UpTo 10mm

No Image

19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Dented
Over 2 UpTo 10mm

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Wing osf
Chipped
1 To 5

No Image



23: Wing osf
Scratched
Over 25mm Not Thru Paint

24: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK