



VEHICLE INSPECTION REPORT

LF19AJN

Ford Focus 1.5 EcoBlue 120 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present

nama
GRADE
5

Details

Reg. date	24/07/2019	Body Style	Hatchback	MOT Due	23/07/2026
Year	2019	Service history	Yes	Gearbox	MANUAL
Mileage	131,306 Miles Warranted	Service documents	Printout	Gears	6
Fuel Type	Diesel	Number of stamps	12	Doors	5
Colour	BLACK	Last service date	17/12/2025		
VIN	WF0NXXGCHNKE10137	Last service miles	126,774		

Last Service - 17.12.2025 at 126774 miles (12 services) EML light on
 Car has been plugged in and detects mass air flow sensor in range but lower than expected
 MAP mass or volume air flow correlation

Tyres

NSF	BUDGET	5.0mm
NSR	FALKEN	4.0mm
OSF	BUDGET	5.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
Up To 25mm Thru Paint



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Dented
With Paint Damage




9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Door osr
Dented
Over 30mm



15: Door osf
Poor Previous Repair
Rippled UpTo 30%



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK