



VEHICLE INSPECTION REPORT

GP16NZA

Kia Ceed 1.4 SR7 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/08/2016	Body Style	Hatchback	Last service miles	97,349
Year	2016	Keys	1	MOT Due	30/11/2026
Mileage	102,257 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	10	Doors	5
VIN	U5YHM51BLGL208658	Last service date	05/11/2025		

£100 ADDITIONAL FEE.

Last service 05/11/2025 at 97,349 miles- 10 main dealer services. Book and print
 Date of service at 57,557 miles not recorded

Tyres

NSF	RAPID	5.0mm
NSR	GT RADIAL	4.0mm
OSF	GT RADIAL	5.0mm
OSR	GT RADIAL	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Door nsr
Dented
Over 30mm



8: Sill ns
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Chipped
Edge Chip



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
Up To 25mm Thru Paint



14: Door nsf
Scratched
Over 25mm Thru Paint



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK