



VEHICLE INSPECTION REPORT

GY61VKW

Ford Focus 1.6 TDCi 115 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE 5

Details

Reg. date	30/11/2011	Body Style	Hatchback	Last service miles	68,104
Year	2011	Keys	2	MOT Due	08/10/2026
Mileage	102,793 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	8	Doors	5
VIN	WF0KXXGCBKBE51166	Last service date	22/11/2019		

£90 ADDITIONAL FEE

Last service 22/11/2019 at 68,104 miles- 8 services (2 main dealer). Book Engine shake while idle
 Condensation in both headlights

Tyres

NSF	KUMHO	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	KUMHO	5.0mm
OSR	YOKOHAMA	5.0mm

Spare

Features


- Bluetooth connection
- Radio/CD
- Full size spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Fogdriving Lamp osf
Broken
Replace




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Bumper Rear
Dented
With Paint Damage



11: Tailgate
Dented
With Paint Damage




12: Bumper Rear Moulding
Broken
Replace



13: Wheel osr
Scratched
Over 50mm



14: Bumper Rear
Insecure
Action Required



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
1 To 5



21: Handle Outer nsr
 Scratched (Painted)
 Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK