



VEHICLE INSPECTION REPORT

GY70UAF

MG Mg 5 EXCLUSIVE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/10/2020	Body Style	Estate	Last service miles	74,289
Year	2020	Keys	2	MOT Due	06/12/2026
Mileage	100,853 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	SILVER	Number of stamps	4		
VIN	LSJE24094LG059665	Last service date	07/05/2024		

£90 ADDITIONAL FEE

Last service 07/05/2024 at 74,289 miles- 4 services. Print Type 3 charging cable

Tyres


NSF	BRIDGESTONE	5.0mm
NSR	FALKEN	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	GT RADIAL	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint




9: Qtr Panel nsr
Dented
Over 30mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: B Post os
Poor Previous Repair
Rippled UpTo 30%



12: B Post ns
Dented
Over 30mm



13: Roof
Dented
Over 30mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Corroded
Light



16: Door osr
Dented
Over 30mm



17: Sill os
Dented
Over 30mm



18: Door osf
Chipped
Edge Chip



19: Wing osf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK