

VEHICLE INSPECTION REPORT

GU64XWG

Peugeot 3008 1.6 HDi Allure 5dr

nama
 GRADE
3

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

Details

| | | | | | |
|-----------|----------------------------|-----------------|-------------------|---------|--------|
| Reg. date | 22/10/2014 | VIN | VF30U9HD8ES196478 | Gearbox | MANUAL |
| Year | 2014 | Body Style | Hatchback | Gears | 6 |
| Mileage | 106,051 Miles Warranted | Keys | 2 | Doors | 5 |
| Fuel Type | Diesel | Service history | None | | |
| Colour | WHITE | MOT Due | 26/10/2026 | | |

no service history Vibration when revving

Tyres

| | | |
|-------|-------------|-------|
| NSF | CONTINENTAL | 3.0mm |
| NSR | RAPID | 5.0mm |
| OSF | CONTINENTAL | 4.0mm |
| OSR | RAPID | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Scratched
Over 25mm Not Thru Paint



3: Door osf
Dented
Over 30mm



4: Door osr
Dented
Between 10mm + 30mm



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Tailgate
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
Edge Chip



12: Door nsf
Chipped
Edge Chip



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|-------|--|----|
| Engine Runs | Fault | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |