



VEHICLE INSPECTION REPORT

KM07GAU

Volkswagen Golf 1.9 Sport TDI 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	11/04/2007	Body Style	Hatchback	Last service miles	131,363
Year	2007	Keys	2	MOT Due	22/03/2026
Mileage	139,173 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	12	Doors	5
VIN	WVVZZZ1KZ7W218053	Last service date	16/03/2023		

£90 ADDITIONAL FEE

Last service 16/03/2023 at 131,363 miles- 12 services (3 main dealer) Book and print Radio missing
Nsr door will not open
Car smokes
Heater blower only works on number 4
Front brakes are rubbing and smoking
Roof lining dropped, door lining dropped

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm

Spare

Features


- PAS
- Electric sunroof
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door Pad nsf
Torn
Over 10mm



2: Door Pad osr
Torn
Over 10mm



3: Roof Lining
Scuffed
Over 25mm



4: Fascia Trim
Damaged
Replace




5: Seat Base Cover osf
Burn
Over 3mm



6: Bonnet
Chipped
Multiple Chips



7: Bumper Front
Chipped
Multiple Chips




8: Wing nsf
Chipped
Multiple Chips




9: Wheel nsf
Scratched
Over 50mm



10: Sill ns
Scratched
Over 25mm Thru Paint



11: Door nsf
Dented
With Paint Damage



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Bumper Rear
Scratched
Over 100mm Thru Paint



16: Tailgate
Rusted
Over 5mm



17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Scratched
Rusted



19: Wheel osr
Scratched
Over 50mm



20: Door osr
Scratched
Rusted



21: Door osf
Dented
Over 30mm



22: Wing osf
Scratched
Rusted



23: Wheel osf
Scratched
Over 50mm



24: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Poor
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	Fault
Windows	OK	Steering	OK