

# VEHICLE INSPECTION REPORT

**OE11ERX**

## BMW 3 Series 330d M Sport 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	09/06/2011	Body Style	Convertible	Last service miles	96,982
Year	2011	Keys	2	MOT Due	21/01/2027
Mileage	111,800 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6		
VIN	WBADY720X0E467765	Last service date	24/01/2020		

£90 ADDITIONAL FEE.

Last service 24/01/2020 at 96982 miles (6 services (4 main dealer). Noisy engine Smoking

### Tyres

NSF	BRIDGESTONE	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm


Spare

## Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Insurance telematics
- Remote central locking
- Navigation system
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Sill Panel Trim ns  
Scratched (Painted)  
Over 25mm Thru Paint



5: Door nsf  
Dented  
Over 30mm



6: Door nsf  
Scratched  
UpTo 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Chipped  
1 To 5



9: Bumper Rear  
Dented  
With Paint Damage



10: Boot Lid  
Scratched  
Over 25mm Thru Paint



11: Wheel osr  
Scratched  
Over 50mm



12: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



13: Door osf  
Scratched  
UpTo 25mm Thru Paint



14: A Post os  
Scratched  
UpTo 25mm Thru Paint



15: Wing osf  
Scratched  
UpTo 25mm Thru Paint

16: Seat Back Cover osf  
Scuffed  
Over 25mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		