



VEHICLE INSPECTION REPORT

SJ14LTA

Nissan Qashqai 1.2 DiG-T Acenta Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	19/03/2014	Body Style	Hatchback	Last service miles	70,867
Year	2014	Keys	2	MOT Due	29/01/2027
Mileage	80,346 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	9	Doors	5
VIN	SJNFEAJ11U1033184	Last service date	16/01/2025		

Last Service - 16.01.2025 at 70867 miles (9 services) Rattling sound coming from engine

Tyres

NSF	DAVANTI	5.0mm
NSR	DAVANTI	6.0mm
OSF	DAVANTI	4.0mm
OSR	DAVANTI	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: A Post ns
Dented
2 Or Less UpTo 10mm



10: Bumper Rear
Poor Previous Repair
Paint Flake



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Dented
Between 10mm + 30mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
1 To 5



15: Wing osf
 Scratched
 UpTo 25mm Thru Paint

16: Lamp osr
 Broken
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		