



VEHICLE INSPECTION REPORT

GN16OFH

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Cat: N
Inspection

Serious Damage? No

Vehicle

VAT Margin
V5 Present

nama
 GRADE
5

Details

| | | | | | |
|------------------|------------------------|--------------------------|--------------|---------------------------|------------|
| Reg. date | 04/03/2016 | Body Style | Hatchback | Last service miles | 89,631 |
| Year | 2016 | Keys | 2 | MOT Due | 16/11/2026 |
| Mileage | 90,445 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Petrol | Service documents | Service Book | Gears | 5 |
| Colour | BLUE | Number of stamps | 6 | Doors | 5 |
| VIN | WF0DXXGAKDFJ69670 | Last service date | 26/01/2026 | | |

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair
 Last Service -26.01.2026 at 89631 miles (6 services) Exhaust blowing

Tyres

| | | |
|--------------|------|-------|
| NSF | TOYO | 5.0mm |
| NSR | TOYO | 5.0mm |
| OSF | TOYO | 5.0mm |
| OSR | TOYO | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Radio/CD
- Full size spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Poor Previous Repair
Poor Paint




4: Wheel nsf
Scratched
Over 50mm



5: A Post ns
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Roof
Scratched
Over 25mm Thru Paint



16: Door Mirror Assy osf
Broken
Replace



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Door osr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |