

VEHICLE INSPECTION REPORT

GV190KX

Mazda CX-5 2.2d Sport Nav+ 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	18/05/2019	Keys	2	CAP Clean	£12,750.00
Year	2019	Service history	Yes	CAP Average	£11,550.00
Mileage	47,292 Miles Warranted	Service documents	Printout	CAP Below	£10,350.00
		Number of stamps	4	Gearbox	AUTOMATIC
Fuel Type	Diesel	Last service date	20/04/2023	Gears	6
Colour	RED	Last service miles	31,632		
VIN	JMZKF6W1A00842970	MOT Due	17/05/2026		
Body Style	Estate				

Last Service -20.04.2023 at 31632 miles (4 main dealer services)

•	VIES
-	,

NSF	TOYO	3.0mm	
NSR		3.0mm	
OSF	тоуо	2.0mm	
OSR	ТОУО	2.0mm	
Spare			

Features

- Bluetooth connection • PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
 Remote central locking
- Cruise control
- Rear parking sensor Digital radio
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Side airbagsLeather seat trim
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front head restraints
- Rear headrests
- Drivers airbag Traction control
- Alloy wheels


- · Heated front seat
- Steering wheel mounted controls
 Electric door mirrors
- Electrically adjustable drivers seat Electrically adjustable passenger seat
 - Height adjustable drivers seat
 - Metallic Paint
 - · Isofix child seat anchor points
 - Central locking

Photos










Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Wheel nsf Scratched Up To 50mm

No Image

4: Wing nsf Scratched Over 25mm Not Thru Paint



5: Door nsf Chipped 1 To 5

No Image

6: Door nsr Scratched Over 25mm Not Thru Paint

No Image

7: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



8: Bumper Rear Chipped Multiple Chips



9: Boot Lid Chipped 1 To 5



10: Door osrChipped1 To 5



11: Door osfChipped1 To 5



12: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated OK	Oil warning light illuminated OK
Airbag light illuminated OK	DPF light illuminated OK
ABS light illuminated OK	Service indicator light illuminated OK
Windows OK	Radio OK
Sat nav OK	Steering OK