



VEHICLE INSPECTION REPORT

BF12RBX

Audi A3 1.6 TDI Sport 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama
GRADE
4

Details

Reg. date	05/03/2012	Body Style	Hatchback	Last service miles	97,726
Year	2012	Keys	2	MOT Due	04/08/2026
Mileage	112,897 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	10	Doors	5
VIN	WAUZZZ8P7CA115533	Last service date	24/05/2023		

Last service 24/05/2023 at 97,726 miles- 10 services (3 main dealer) Book
 Date of service at 60,386 miles not recorded
 NO V5 Car shake when idle
 Service due message displayed
 Condensation in lights

Tyres

NSF	BRIDGESTONE	4.0mm
NSR	AVON	4.0mm
OSF	AUTOGREEN	4.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check




Damage Photos



1: Glove Box Lid
Broken
Replace



2: Other
N/A
N/A



3: Carpets Rear
Missing
Replace



4: Bonnet
Poor Previous Repair
Paint Flake



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Poor Previous Repair
Poor Paint



8: Screen Front
Chipped
UpTo 10mm



9: Door nsf
Dented
Between 10mm + 30mm



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Chipped
1 To 5



12: Door nsr
Dented
2 Or Less Up To 10mm



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Tailgate
Chipped
1 To 5



16: Lamp osr
Broken
Replace



17: Bumper Rear
Dented
With Paint Damage



18: Wheel osr
Scratched
Over 50mm



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Door osr
Dented
With Paint Damage



21: Handle Outer osr
Scratched (Painted)
Over 25mm Thru Paint



22: Door osf
Chipped
1 To 5



23: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



24: Roof
Chipped
1 To 5



25: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK