



VEHICLE INSPECTION REPORT

DN21UJC

Vauxhall Corsa 1.2 Turbo SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/04/2021	Body Style	Hatchback	Last service miles	55,271
Year	2021	Keys	2	MOT Due	28/04/2026
Mileage	58,967 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	VXKUPHNEKM4160154	Last service date	31/10/2025		

£90 ADDITIONAL FEE

Last service 31/10/2025 at 55,271 miles- 5 services. Book and print
 Timing belt replaced 18/11/2025 at 55,318 miles Parking camera faulty

Tyres

NSF	RAPID	5.0mm
NSR	RAPID	5.0mm
OSF	RAPID	5.0mm
OSR	BUDGET	5.0mm


Spare

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
Between 10mm + 30mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
1 To 5



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Roof
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Chipped
1 To 5




14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Chipped
1 To 5



17: Screen Front
Chipped
Over 10mm



18: Wheel osf
Scratched
Over 50mm



19: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK