



VEHICLE INSPECTION REPORT

DN71UXC

Peugeot 2008 100kW GT 50kWh 5dr Auto

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/12/2021	Body Style	Hatchback	Last service miles	25,940
Year	2021	Keys	2	MOT Due	30/12/2026
Mileage	27,334 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Service Book	Gears	1
Colour	WHITE	Number of stamps	2	Doors	5
VIN	VR3UKZKXZMJ908800	Last service date	06/12/2025		

£90 ADDITIONAL FEE

Last service 06/12/2025 at 25,940 miles- 2 services (1 main dealer) Book Type 2 charging cable only

Tyres

NSF	GOODYEAR	4.0mm
NSR	MICHELIN	5.0mm
OSF	RAPID	7.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front Moulding
Scratched (Painted)
Up To 25mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: A Post ns
Chipped
1 To 5



5: Door nsf
Chipped
Edge Chip



6: Wheel nsr
Scratched
Up To 50mm



7: Door osr
Dented
2 Or Less UpTo 10mm



8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



10: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK