



VEHICLE INSPECTION REPORT

WF58MGU

Audi A3 2.0 TDI 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE 5

Details

Reg. date	08/01/2009	Body Style	Hatchback	Last service miles	169,487
Year	2009	Keys	1	MOT Due	03/03/2027
Mileage	190,535 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	9	Doors	5
VIN	WAUZZZ8P39B015772	Last service date	30/04/2020		

Last service 30/04/2020 at 169,487 miles- 9 services (3 main dealer) Book
 Date of service at 92,978 miles not recorded Seats heavily stained
 EML light on car has been plugged in and detects intake manifold runner position sensor switch circuit range
 bank 1
 Headlight need attention clouded and condensation
 Driver side window will not open

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage



2: Wheel of
Scratched
Up To 50mm



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osf
Scratched
Over 25mm Not Thru Paint



6: Door osr
Dented
2 Or Less Up To 10mm



7: Qtr Panel osr
Dented
With Paint Damage



8: Door osr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Door nsr
Dented
2 Or Less Up To 10mm



14: Door nsf
Scratched
Over 25mm Not Thru Paint



15: Wing nsf
Dented
With Paint Damage



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Poor Previous Repair
Paint Flake



18: Screen Front
Cracked
Replace



19: Roof
Chipped
1 To 5



20: Wheel osr
Scratched
Over 50mm



21: Wheel nsf
Scratched
Up To 50mm



22: Door Mirror Assy nsf
Broken
Replace



23: Other
N/A
N/A



24: Other
N/A
N/A



25: Other
N/A
N/A



26: Other
N/A
N/A



27: Sill os
Chipped
Over 5mm



28: Other
N/A
N/A



29: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK