



# VEHICLE INSPECTION REPORT

**GX68UJF**

## Citroen C3 1.6 BlueHDi 100 Feel 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE 3

### Details

Reg. date	29/09/2018	Body Style	Hatchback	Last service miles	100,953
Year	2018	Keys	2	MOT Due	21/08/2026
Mileage	113,945 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	6	Doors	5
VIN	VF7SXBHY6JT587067	Last service date	26/07/2025		

£90 ADDITIONAL FEE.

Last service 26/07/2025 at 100,953 miles- 6 services (4 main dealer) Book Spanner light and eml on dash  
 Scanner will not read says data link error  
 Front bumper out of line and has popped out of place on near side

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim
- Navigation system
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Corroded  
Light



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
Edge Chip



4: Door osf  
Scratched  
UpTo 25mm Not Thru Paint



5: Wheel osr  
Corroded  
Light



6: Qtr Panel osr  
Dented  
Between 10mm + 30mm



7: Tailgate  
Chipped  
1 To 5



8: Bumper Rear  
Chipped  
1 To 5



9: Wheel nsr  
Corroded  
Light



10: Door nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsr  
Dented  
2 Or Less UpTo 10mm



12: Door nsf  
Scratched  
Over 25mm Not Thru Paint



13: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint



14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint




15: Wheel nsf  
Corroded  
Light



16: Bumper Front  
Scratched  
Over 100mm Thru Paint



17: Bonnet  
Chipped  
Multiple Chips



18: Screen Front  
Chipped  
UpTo 10mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK