



VEHICLE INSPECTION REPORT

HK67XCN

Renault Kadjar 1.5 dCi Signature Nav 5dr EDC

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/01/2018	Body Style	Hatchback	Last service miles	67,960
Year	2018	Keys	2	MOT Due	06/04/2026
Mileage	80,516 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	6	Doors	5
VIN	VF1RFE00758639700	Last service date	04/10/2024		

Last service 04/10/2024 at 67,960 miles- 6 services (3 main dealer) Print Intermittent gear selection fault

Tyres

NSF	NEXEN	4.0mm
NSR	ACCELERA	4.0mm
OSF	NEXEN	4.0mm
OSR	ACCELERA	4.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Wheel of
Scratched
Over 50mm



3: Wheel osr
Corroded
Light



4: Wheel nsr
Corroded
Light



5: Wheel nsf
Corroded
Light



6: Wing osf
Chipped
1 To 5



7: Wing osf
Scratched
Over 25mm Not Thru Paint



8: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



9: Door osf
Chipped
Edge Chip



10: Door osr
Scratched
Over 25mm Not Thru Paint



11: Door osr
Chipped
Edge Chip



12: Door osr
Chipped
Edge Chip



13: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



14: Tailgate
Dented
Over 30mm



15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Qtr Panel Moulding ns
Broken
Replace




17: Door nsr
Scratched
Over 25mm Thru Paint



18: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




19: Door nsf
Dented
With Paint Damage



20: Wing nsf
Dented
With Paint Damage



21: Bumper Front
Poor Previous Repair
Poor Paint



22: Bonnet
Poor Previous Repair
Poor Paint



23: Boot Lid
Poor Previous Repair
Paint Flake



24: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		