



VEHICLE INSPECTION REPORT

YS14DXP

Ford Grand C-Max 1.6 TDCi Titanium 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	09/06/2014	Body Style	MPV	Last service miles	85,017
Year	2014	Keys	1	MOT Due	23/07/2026
Mileage	114,368 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	10		
VIN	WF0HXXWPBHET29237	Last service date	05/06/2023		

Last service 05/06/2023 at 85,017 miles- 10 services (7 main dealer) Book Oil change due
 Rear drivers door open only from inside

Tyres

NSF	BUDGET	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm



Spare

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Not Thru Paint



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Not Thru Paint



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Door nsf
Chipped
Edge Chip



12: Door nsf
Scratched
Over 25mm Not Thru Paint



13: Wing nsf
Scratched
Over 25mm Not Thru Paint



14: Wheel nsf
Scratched
Over 50mm




15: Wing nsf
Scratched
UpTo 25mm Thru Paint



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: Roof
Scratched
Over 25mm Not Thru Paint



19: Seat Back Cover nsr
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK