

VEHICLE INSPECTION REPORT

VX15UEK

Kia Sportage 1.7 CRDi ISG 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	07/03/2015	Body Style	Estate	Last service miles	168,428
Year	2015	Keys	2	MOT Due	09/06/2026
Mileage	173,968 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	9		
VIN	U5YPC815LEL609398	Last service date	06/12/2025		

Last service 06/12/2025 at 168,428 miles- services (3 main dealer) Book Noisy brakes
Roof need attention it's opening a bit then start to slow down

Tyres

NSF	GT RADIAL	6.0mm
NSR	GT RADIAL	6.0mm
OSF	GT RADIAL	6.0mm
OSR	GT RADIAL	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Full size spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Screen Front
Cracked
Replace



6: Roof
Scratched
UpTo 25mm Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsf
Chipped
Multiple Chips



10: Door nsr
Dented
Over 30mm



11: Door nsr
Chipped
Multiple Chips



12: Qtr Panel nsr
Chipped
1 To 5



13: Wheel nsr
Scratched
Over 50mm



14: Tailgate
Dented
Over 30mm



15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Bumper Rear
Scratched
Up To 25mm Thru Paint



17: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Dented
With Paint Damage



20: Door osf
Chipped
Edge Chip



21: Door osf
Dented
Over 30mm



22: Wing osf
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK