



# VEHICLE INSPECTION REPORT

**LS65EYV**

## Nissan Juke 1.6 [94] Visia 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	23/09/2015	Body Style	Hatchback	Last service miles	66,281
Year	2015	Keys	2	MOT Due	23/09/2026
Mileage	69,389 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	9	Doors	5
VIN	SJNFBAF15U7157991	Last service date	16/09/2025		

£90 ADDITIONAL FEE.

Last service 16/09/2025 at 66281 miles (9 services). EML light on

Car been plugged in and detected;

low voltage issue in the heater control circuit of the downstream oxygen sensor (Bank 1, Sensor 2).

### Tyres

NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	RAPID	6.0mm
Spare		

## Features


- Rear wiper
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



3: Bumper Front  
Chipped  
Multiple Chips



4: Wheel nsf  
Scratched  
Over 50mm



5: A Post ns  
Chipped  
1 To 5



6: Door nsf  
Dented  
With Paint Damage



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



10: Roof  
Dented  
Over 30mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint




12: Tailgate  
Scratched  
UpTo 25mm Thru Paint




13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Door nsr  
Dented  
Between 10mm + 30mm



15: Door nsr  
Scratched  
Over 25mm Thru Paint



16: Door nsf  
Scratched  
Over 25mm Thru Paint



17: Wing osf  
Chipped  
Multiple Chips



18: Screen Front  
Chipped  
UpTo 10mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK