



VEHICLE INSPECTION REPORT

KV19MXA

Citroen Berlingo 1.2 PureTech Flair M 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2019	Keys	2	CAP Clean	£8,450.00
Year	2019	Service history	Yes	CAP Average	£7,450.00
Mileage	95,500 Miles Warranted	Service documents	Service Book	CAP Below	£6,475.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	GREY	Last service date	04/02/2025	Gears	6
VIN	VR7ERHNPJKJ581009	Last service miles	91,743		
Body Style	MPV	MOT Due	28/02/2026		

Last Service - 04.02.2025 at 91743 miles (7 services) Heavy vibration at idle and passenger rear window fault

Tyres

NSF	HANKOOK	2.0mm
NSR	ROTALLA	4.0mm
OSF	HANKOOK	2.0mm
OSR	ROTALLA	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Auxiliary input socket
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos




1: Boot Lid
Chipped
1 To 5



2: Door or
Dented
With Paint Damage



3: Door osf
Dented
With Paint Damage



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Scratched
Over 50mm



6: Wheel osf
Scratched
Up To 50mm




7: Wing osf
Scratched
Over 25mm Thru Paint




8: Bonnet
Chipped
1 To 5



9: Bumper Front
Scratched
25 to 100mm Thru Paint



10: Bumper Front
Scratched
Over 25mm Not Thru Paint



11: Wing nsf
Scratched
Over 25mm Not Thru Paint



12: Wheel nsf
Scratched
Up To 50mm



13: Door nsf
Chipped
1 To 5



14: Door osf
Dented
With Paint Damage



15: Qtr Panel nsr
Dented
With Paint Damage



16: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK