



# VEHICLE INSPECTION REPORT

**KP64WJL**

## Peugeot 208 1.0 VTi Active 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

### Details

Reg. date	31/10/2014	Body Style	Hatchback	Last service miles	56,974
Year	2014	Keys	2	MOT Due	20/06/2026
Mileage	57,798 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	11	Doors	5
VIN	VF3CCZMZ0ET102940	Last service date	21/06/2025		

No V5.

Last service 21/06/2025 at 56974 miles (11 services (7 main dealer). Engine tapping

### Tyres


NSF	TOMKET	5.0mm
NSR	SAILUN	4.0mm
OSF	GOODYEAR	5.0mm
OSR	TOMKET	5.0mm
Spare		

## Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



3: Wing nsf  
Chipped  
1 To 5



4: Wheel nsf  
Scratched  
Over 50mm




5: Screen Front  
Chipped  
Over 10mm



6: Door nsf  
Dented  
Over 30mm



7: Door nsf  
Scratched  
Up To 25mm Thru Paint



8: Door nsr  
Dented  
Between 10mm + 30mm



9: Wheel nsr  
Corroded  
Light



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Bumper Rear  
Dented  
With Paint Damage



12: Qtr Panel osr  
Poor Previous Repair  
Rippled Up To 30%



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Poor Previous Repair  
Rippled Up To 30%



15: Door osf  
Dented  
Over 30mm



16: Wing osf  
Scratched  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK