



# VEHICLE INSPECTION REPORT

**CU19YRG**

## Vauxhall Insignia 2.0 Turbo D SRi Vx-line Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	29/03/2019	Body Style	Estate	Last service miles	76,556
Year	2019	Keys	2	MOT Due	31/03/2026
Mileage	83,695 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	5		
VIN	W0VZS8EG3K1054773	Last service date	17/03/2025		

### £90 ADDITIONAL FEE

Last service 17/03/2025 at 76,556 miles- 5 services. Book and print Eml light is on  
Car been scanned and detected:

Exhaust Gas Recirculation (EGR) Flow Insufficient

P-12A6 typically indicates a severe fault within the Fuel Pump Control Module (FPCM), often caused by an internal capacitor failure

Service due message displayed

### Tyres

NSF	MAZZINI	Punctured
NSR	MAZZINI	5.0mm
OSF	SAILUN	5.0mm
OSR	MAZZINI	5.0mm

### Spare

## Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm




4: Door Mirror Assy nsf  
Broken  
Replace



5: Door nsf  
Dented  
With Paint Damage



6: Door nsr  
Dented  
Between 10mm + 30mm



7: Door nsr  
Chipped  
1 To 5



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint




10: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Tailgate  
Dented  
2 Or Less Up To 10mm



13: Qtr Panel osr  
Dented  
Between 10mm + 30mm



14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Poor Previous Repair  
Rippled UpTo 30%



16: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



17: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



18: Wheel osf  
Scratched  
Over 50mm



19: Wing osf  
Dented  
2 Or Less UpTo 10mm



20: Sill Panel Trim ns  
Scratched (Painted)  
Over 25mm Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK