



VEHICLE INSPECTION REPORT

AK09HCJ

Ford Fiesta 1.25 Zetec 5dr [82]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy

nama
GRADE 5

Details

Reg. date	09/04/2009	Body Style	Hatchback	MOT Due	11/11/2026
Year	2009	Keys	1	Gearbox	MANUAL
Mileage	106,993 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Petrol	Number of stamps	2	Doors	5
Colour	BLACK	Last service date	20/04/2016		
VIN	WF0JXXWPJJ9U57615	Last service miles	43,883		

PHOTOCOPY OF V5

Last service 20/04/2016 at 43,883 miles- 2 main dealer services confirmed by Trustford, Dagenham Noisy suspension

Tyres

NSF	BUDGET	4.0mm
NSR	JOYROAD	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm


Spare

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos




1: Seat Back Cover of
Holed
Over 3mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Cracked
Over 25mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Broken
Replace



7: A Post ns
Scratched
Up To 25mm Thru Paint



8: Aperture Seal nsf
Broken
Replace



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Poor Previous Repair
Rippled Up To 30%



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: A Post ns
Dented
Between 10mm + 30mm



15: Tailgate
Dented
Between 10mm + 30mm



16: Bumper Reflector osr
Broken
Replace



17: Qtr Panel osr
Dented
With Paint Damage



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Dented
Over 30mm



20: Roof
Scratched
Over 25mm Thru Paint



21: Door osf
Dented
With Paint Damage



22: Wing osf
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Seat Back Cover nsf
Scuffed
Over 25mm



25: Sill ns
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK