

VEHICLE INSPECTION REPORT

GV64DSZ

Toyota Yaris 1.33 VVT-i Icon 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/12/2014	Body Style	Hatchback	Last service miles	75,051
Year	2014	Keys	2	MOT Due	18/12/2026
Mileage	77,129 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	1
Colour	RED	Number of stamps	11	Doors	5
VIN	VNKKJ3D390A262094	Last service date	21/01/2025		

Last Service - 21.01.2025 at 75051 miles (11 main dealer services)

Tyres

NSF	FALKEN	4.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	5.0mm


Spare

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Park assist camera
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm




5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: A Post ns
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Up To 50mm



14: Door osr
Scratched
Over 25mm Thru Paint




15: Door Mirror Assy osf
 Scratched (Painted)
 Over 25mm Thru Paint



16: Door osf
 Scratched
 Over 25mm Thru Paint



17: Wing osf
 Chipped
 1 To 5



18: Wheel osf
 Scratched
 Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK