



# VEHICLE INSPECTION REPORT

**GY67DWJ**

## Volkswagen Tiguan 2.0 TSi 180 4Motion SEL 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	18/10/2017	Keys	2	CAP Clean	£13,000.00
Year	2017	Service history	Yes	CAP Average	£11,750.00
Mileage	84,654 Miles Warranted	Service documents	Service Book	CAP Below	£10,500.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	SEMI AUTO
Colour	BLUE	Last service date	10/07/2024	Gears	7
VIN	WVGZZZ5NZJW328019	Last service miles	74,375		
Body Style	Estate	MOT Due	13/07/2025		

£65 ADDITIONAL FEE

Last Service - 10.07.2024 at 74375 miles (7 services()) sun roof leaking

### Tyres

NSF	PIRELLI	3.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	3.0mm
OSR	PIRELLI	3.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Auxiliary input socket
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- PAS
- Trip computer
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Bumper Front Moulding  
Broken  
Replace



4: Wing nsf  
Dented  
With Paint Damage




5: Wheel nsf  
Scratched  
Up To 50mm



6: Door nsf  
Dented  
Over 30mm



7: Door nsr  
Chipped  
1 To 5



8: Door nsr  
Scratched  
Over 25mm Not Thru Paint





9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Boot Lid  
Dented  
Over 2 UpTo 10mm



12: Wheel osr  
Scratched  
Up To 50mm




13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Door osr  
Dented  
Over 30mm



15: Door osf  
Dented  
Over 2 UpTo 10mm



16: Wing osf  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osf  
Scratched  
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		