



VEHICLE INSPECTION REPORT

YC57MHY

BMW 3 Series 318i SE 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/09/2007	VIN	WBAVA52070VB19812	Gearbox	MANUAL
Year	2007	Body Style	Saloon	Gears	6
Mileage	91,555 Miles Warranted	Keys	1	Doors	4
Fuel Type	Petrol	Service history	None		
Colour	BLACK	MOT Due	20/08/2026		

£65 ADDITIONAL FEE

No service history EML light on car has been plugged in and detects
 Mass air flow sensor circuit
 O2 sensor circuit slow response after coast down
 Fuel cut off bank 2 sensor 1
 Service light on nsf window doesn't work and osf window doesn't work

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	KUMHO	5.0mm

Spare

Features


- Cruise control
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Scratched
Over 25mm Not Thru Paint



3: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Chipped
1 To 5



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Poor Paint




10: Tailgate
Scratched
Over 25mm Not Thru Paint



11: Lamp osr
Broken
Replace



12: Qtr Panel nsr
Chipped
1 To 5



13: Wheel nsr
Scratched
Over 50mm



14: Door nsr
Dented
Over 30mm



15: Door nsf
Chipped
Edge Chip



16: Door nsf
Chipped
1 To 5



17: Wheel nsf
Scratched
Over 50mm



18: Wing nsf
Chipped
1 To 5



19: Bumper Front
Poor Previous Repair
Poor Paint



20: Bonnet
Chipped
1 To 5



21: Other
N/A
N/A

22: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK