



VEHICLE INSPECTION REPORT

AF14KNJ

Dacia Sandero 1.2 16V Ambiance 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/03/2014	Body Style	Hatchback	Last service miles	68,442
Year	2014	Keys	1	MOT Due	30/03/2026
Mileage	135,774 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	5	Doors	5
VIN	UU15SDAG350493326	Last service date	25/10/2019		

£100 ADDITIONAL FEE

Last Service - 25.10.2019 at 68442 miles (5 services) Boot will not open
 Key broken buttons

Tyres

NSF	BARUM	Damaged
NSR	KUMHO	5.0mm
OSF	BARUM	2.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Drivers airbag
- Traction control
- Steel wheels
- PAS
- Folding rear seats
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Media storage
- Front head restraints
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Screen Front
Chipped
Over 10mm



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsf
Dented
Over 30mm



7: Sill ns
Dented
Over 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel Trim nsr
Missing
Replace



10: Bumper Rear
Cracked
UpTo 25mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Tailgate
Dented
With Paint Damage



13: Other
N/A
N/A



14: Qtr Panel osr
Dented
With Paint Damage



15: Door osr
Dented
Between 10mm + 30mm



16: Door osf
Chipped
Edge Chip



17: Sill os
Rusted
Holed



18: Flasher Side Repeater os
Broken
Replace



19: Wing osf
Dented
Between 10mm + 30mm



20: Roof
Dented
Over 30mm



21: Tyre nsf
 Damaged
 Replace



22: Air Vents osf
 Missing
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK