



VEHICLE INSPECTION REPORT

GX16KLF

Toyota Yaris 1.33 VVT-i Design 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	04/03/2016	Body Style	Hatchback	Last service miles	19,691
Year	2016	Keys	2	MOT Due	10/03/2027
Mileage	20,596 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED/BLACK	Number of stamps	9	Doors	5
VIN	VNKKJ3D350A342105	Last service date	19/02/2025		

Last Service - 19.02.2025 at 19691 miles (9 main dealer services)

Tyres

NSF	MICHELIN	5.0mm
NSR	FALKEN	5.0mm
OSF	MICHELIN	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Digital radio
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Wheel nsf
Scratched
Up To 50mm



3: Wing nsf
Chipped
1 To 5




4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Chipped
1 To 5



9: Door osr
 Scratched
 Over 25mm Thru Paint



10: Door osf
 Scratched
 Over 25mm Thru Paint



11: Door Mirror Assy osf
 Broken
 Replace



12: Wheel osf
 Scratched
 Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK