



VEHICLE INSPECTION REPORT

DU66XVX

Vauxhall Corsa 1.4 ecoFLEX SRi 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/11/2016	Body Style	Hatchback	Last service miles	44,710
Year	2016	Keys	2	MOT Due	27/06/2026
Mileage	77,589 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	1	Doors	5
VIN	W0L0XEP68H4065965	Last service date	16/09/2020		

Last Service - 16.09.2020 at 44710 miles (1 main dealer services) Service tyre monitor system light on

Tyres

NSF	BUDGET	3.0mm
NSR	HANKOOK	3.0mm
OSF	NEXEN	Illegal
OSR	BUDGET	5.0mm



Spare

Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing ofsf
Chipped
1 To 5



2: Wheel ofsf
Scratched
Over 50mm



3: Door osf
Dented
With Paint Damage




4: Door osr
Dented
With Paint Damage




5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Bumper Front
Scratched
Over 100mm Thru Paint



9: Wing nsf
Dented
With Paint Damage



10: Wheel nsf
Scratched
Over 50mm



11: Door nsf
Dented
With Paint Damage



12: Door nsr
Scratched
Over 25mm Not Thru Paint



13: Door nsr
Chipped
1 To 5



14: Wheel nsr
Scratched
Over 50mm



15: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint



16: Other
 N/A
 N/A



17: Tailgate
 Chipped
 1 To 5



18: Bonnet
 Dented
 Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK