



VEHICLE INSPECTION REPORT

EK60YTC

Audi A1 1.4 TFSI Sport 3dr S Tronic



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

Details

Reg. date	14/01/2011	Body Style	Hatchback	Last service miles	40,732
Year	2011	Keys	1	MOT Due	05/02/2027
Mileage	94,673 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	BLUE	Number of stamps	2	Doors	3
VIN	WAUZZZ8X9BB032680	Last service date	05/02/2014		

£90 ADDITIONAL FEE.

NO V5

Last Service - 05.02.2014 at 40732 miles (2 main dealer services) Sat nav missing valid SD card

Front screen leaks water inside car

Engine tapping

Tyres

NSF	NEXEN	Damaged
NSR	NANKANG	5.0mm
OSF	FIRESTONE	Damaged
OSR	NANKANG	5.0mm



Spare

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Roof
Dented
Between 10mm + 30mm



2: Bonnet
Poor Previous Repair
Paint Flake



3: Bumper Front
Poor Previous Repair
Poor Paint




4: Fog Lamp Surround ns
Broken
Replace



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Poor Previous Repair
Poor Paint



7: Door nsf
Poor Previous Repair
Rippled UpTo 30%



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



10: Tailgate
Chipped
1 To 5



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



13: Wheel osr
Scratched
Over 50mm



14: Door osf
Poor Previous Repair
Rippled UpTo 30%



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Wheel osf
Scratched
Over 50mm



17: A Post os
Scratched
UpTo 25mm Thru Paint



18: Screen Front
Chipped
UpTo 10mm



19: Roof
Scratched
Over 25mm Thru Paint



20: Carpets Front
Scuffed
Over 25mm



21: Tyre osf
 Damaged
 Replace



22: Tyre nsf
 Damaged
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK