

# VEHICLE INSPECTION REPORT

**GV70GVK**

## Dacia Sandero Stepway 1.0 TCe Bi-Fuel Comfort 5dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

### Details

Reg. date	04/12/2020	Colour	GREY	MOT Due	18/12/2026
Year	2020	VIN	UU1B5220966182174	Gearbox	MANUAL
Mileage	27,763 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Gas Bi Fuel	Keys	2	Doors	5

Orange warning zigzag light display

### Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Roof rails
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



4: Wing nsf  
Chipped  
1 To 5



5: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Chipped  
1 To 5



8: Tailgate  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



10: Door osr  
Chipped  
Edge Chip



11: Door osr  
Scratched  
UpTo 25mm Thru Paint



12: Door osf  
Chipped  
Edge Chip



13: Door osf  
Chipped  
1 To 5



14: Wing Front Arch Extension os  
Scuffed (Unpainted)  
Over 100mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK