



VEHICLE INSPECTION REPORT

GU67JXK

Vauxhall Mokka X 1.4T Active 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	08/09/2017	Body Style	Hatchback	Last service miles	33,523
Year	2017	Keys	2	MOT Due	21/09/2026
Mileage	34,414 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	5	Doors	5
VIN	W0LJC7E8XHB238553	Last service date	22/09/2025		

Last Service - 22.09.2025 at 33523 miles (5 main dealer services)

Tyres

NSF	RAPID	6.0mm
NSR	MAZZINI	6.0mm
OSF	RAPID	6.0mm
OSR	MAZZINI	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint




5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Tailgate
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel osr
Dented
Over 30mm



11: Door osr
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm



13: Door osf
Scratched
UpTo 25mm Thru Paint



14: Wheel osf
Scratched
Over 50mm



15: A Post os
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK