



VEHICLE INSPECTION REPORT

PE16AVG

Volkswagen Golf 1.4 TSI 150 GT Edition 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	14/03/2016	Body Style	Hatchback	Last service miles	111,702
Year	2016	Keys	2	MOT Due	04/02/2027
Mileage	115,009 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	11	Doors	5
VIN	WVWZZZAUZGP081460	Last service date	24/11/2025		

Last Service - 24.11.2025 at 111702 miles (11 services)

Tyres



NSF	FIRESTONE	6.0mm
NSR	FIRESTONE	5.0mm
OSF	FIRESTONE	4.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Grill
Broken
Replace



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
1 To 5



15: Door osf
Chipped
1 To 5



16: Wheel osf
Scratched
Up To 50mm



17: Wing osf
Chipped
1 To 5



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		