



VEHICLE INSPECTION REPORT

LG15SKK

Skoda Yeti Outdoor 2.0 TDI CR [170] Elegance 4x4 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/03/2015	Body Style	Hatchback	Last service miles	94,311
Year	2015	Keys	2	MOT Due	19/11/2026
Mileage	143,036 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREEN	Number of stamps	6	Doors	5
VIN	TMBME75L8F6020680	Last service date	28/02/2020		

Last service 28/02/2020 at 94,311 miles- 6 main dealer services. Print MOTs from 2023 upwards recorded in Km on MOT history
Inspection due

Tyres

NSF	BUDGET	5.0mm
NSR	PIRELLI	5.0mm
OSF	AUTOGREEN	3.0mm
OSR	AUTOGREEN	4.0mm


Spare

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Dented
2 Or Less UpTo 10mm



5: Door osf
Chipped
Edge Chip



6: Door osr
Dented
Over 2 UpTo 10mm



7: Qtr Panel osr
Rusted
Over 5mm



8: Bumper Rear
Chipped
Multiple Chips



9: Tailgate
Rusted
Over 5mm



10: Door nsr
Chipped
1 To 5




11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Door nsf
Dented
Between 10mm + 30mm



13: Wing nsf
Scratched
Over 25mm Thru Paint




14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
 Scratched
 Over 100mm Thru Paint



16: Bonnet
 Scratched
 Over 25mm Thru Paint



17: Screen Front
 Chipped
 UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK